

ਵੱਲੋਂ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ.2 ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਸੰਗਰੂਰ।

ਵੱਲੋਂ

ਪ੍ਰਿੰਸੀਪਲ,
ਰੋਜ਼ਮੈਰੀ ਪਬਲਿਕ ਸਕੂਲ,
ਸੁਨਾਮ।

ਨੰਬਰ: 92

Serial No. Y 675362
20/05/2025
Received from Principal Rosemary Public
School, Sunam.
with letter No. dated 20/05/2025
the sum of Rupees 30,000 [thirty thousand]
in Cash/by Cheque on account of Inspection fee
in Cash payment of Building Safety
Inspection fee
Rs 30,000 only
[Thirty thousand only]
Signature
Sub Divisional Engineer
Cons. Sub Division No. 2
P.W.D. B&R SANGRUR.

ਮਿਤੀ: 22/05/2025

ਵਿਸ਼ਾ:- ਸਾਲ 2025-28 ਦੇ ਲਈ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਪ੍ਰਾਪਤ ਹੋਇਆ ਕੇਸ ਸਬੰਧਿਤ ਜੇ.ਈ. ਵੱਲੋਂ ਲੋੜੀਂਦੀ ਇੰਨਸਪੈਕਸ਼ਨ ਕਰਨ ਉਪਰੰਤ ਸਮੇਤ ਸਰਟੀਫਿਕੇਟ ਆਪ ਜੀ ਨੂੰ ਅਗਲੇਰੀ ਯੋਗ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ। ਲੋੜੀਂਦੀ ਇੰਨਸਪੈਕਸ਼ਨ ਫੀਸ ਬਾਬਤ ਰੁਪਏ 30,000/- (ਤੀਹ ਹਜ਼ਾਰ ਰੁਪਏ ਸਿਰਫ) ਜੀ.ਆਰ. ਨੰ:675362 ਮਿਤੀ: 20.05.2025 ਰਾਹੀਂ ਜਮਾਂ ਕਰਵਾ ਲਈ ਗਈ ਹੈ।

ਇਸ ਤੋਂ ਇਲਾਵਾ ਆਪ ਵੱਲੋਂ ਨਾਲ ਨੱਥੀ ਕੀਤਾ ਗਿਆ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ, ਜਿਸ ਦੀ ਜਾਰੀ ਕਰਨ ਦੀ ਮਿਤੀ: 04/06/2024 ਹੈ, ਦੇ ਸਬੰਧ ਵਿੱਚ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਉਕਤ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਦੀ ਮਿਆਦ 31/03/2028 (ਹਰ ਸਾਲ) ਤੱਕ ਵਧਾਉਣ ਦੀ ਜ਼ਿੰਮੇਵਾਰੀ ਆਪ ਦੀ ਨਿੱਜੀ ਹੋਵੇਗੀ ਅਤੇ ਮਿਆਦ ਵਧਾਉਣ ਉਪਰੰਤ ਇਸ ਦਫਤਰ ਨੂੰ ਸੂਚਿਤ ਕੀਤਾ ਜਾਵੇ ਅਜਿਹਾ ਨਾ ਕਰਨ ਦੀ ਸੂਰਤ ਵਿੱਚ ਇਸ ਦਫਤਰ ਵੱਲੋਂ ਜਾਰੀ ਕੀਤਾ ਗਿਆ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਮਿਤੀ: 04/06/2025 ਤੋਂ ਬਾਅਦ ਰੱਦ ਸਮਝਿਆ ਜਾਵੇਗਾ।

ਨੱਥੀ:- ਸਰਟੀਫਿਕੇਟ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ.2 ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਸੰਗਰੂਰ।

ਪਿੱਠ ਅੰਕਣ ਨੰ.

ਮਿਤੀ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ ਸੰਗਰੂਰ ਜੀ ਨੂੰ ਉਹਨਾਂ ਦੇ ਪੱਤਰ ਨੰ. 1433 ਮਿਤੀ:15.05.2025 ਦੇ ਸਬੰਧ ਵਿੱਚ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ.2 ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਸੰਗਰੂਰ।


Part-II


Building Safety Report

Name of School: ROSEMARY PUBLIC SCHOOL, SUNAM

Sh. Nitin Kumar (Junior Engineer) has visited the above mentioned school on dated 19/05/2025 and on his visual inspection; the building seems to be safe subject to the following observation & conditions.

- a) Parameters to check the stability and safety of building as Architectural Drawings, Bearing capacity, Foundation detail, Structural Drawings, Technical Specifications, Test Reports of Material used, Quality Control reports and certificate from the Engineer in-Charge for construction are not available.
- b) In case any addition, alteration or expansion and modification to this building are done certificate may be obtained after the completion from the undersigned.
- c) In case the building is affected by flood or if there is any settlement of walls/ foundation or sagging of roofs etc. immediate inspection of the undersigned be arranged to check stability and safety of the building.
- d) This Certificate holds validity only with valid Fire Safety Certificate. A separate certificate regarding Fire Fighting should be obtained from the competent Authority. it will be your personal responsibility to extend the period of the said fire safety certificate upto 31/03/2028 (Every Year) and after extending the period, this office should be informed every year, failing which the building safety certificate issued by this office will be considered cancelled with immediate effect.
- e) A separate certificate regarding Electrical works should be obtained from the competent Authority.
- f) The owner of the building / Management is fully responsible regarding safety of the building from all angles in spite of the report.
- g) The covered area of the building is As per Drawings 45229.21Sft.
- h) The report is not valid for legal purpose.
- i) The building visually seems safe to occupy for normal use to Three Year, upto 31-03-2028


(Nitin Kumar)
J.E


Sub Divisional Engineer
Const. Sub Divn.No.2 PWD, B&R
Sangrur.